Sport Hill Road Active Transportation Workshop

Easton, CT

November 15 and 16, 2019




1 Introduction

What's this workshop all about?

State Physical Activity and Nutrition (SPAN) Program











Our Most Vulnerable Users

- 17% of kids and teens are obese.
- Limited physical activity contributes to the obesity epidemic.
- Dedicated, safe space for bicycling and walking help kids be active and gain independence.

Our Most Vulnerable Users

- By 2025, nearly 1 in 5 Americans will be 65 or older.
- About ½ of all non-drivers over the age of 65 would like to get out more often.
- Rural residents are older than general population and suffer from higher rates of physical inactivity and chronic ailments like obesity and diabetes.



Source: U.S. Census Bureau Estimates, 2009 National Household Travel Survey Photo: Dan Burden, Walkable and Livable Communities Institute



Our Most Vulnerable Users

- Nearly 1 in 5 Americans have a disability.
- Complete Streets = attention to detail for travelers with disabilities.
- Complete Streets can reduce isolation and dependence.

Easton Demographics

Under 18: 23.5% (1,785)

Over 65: 17.7% (1,347)

Disabilities: 9.2% (698)

Source: 2017 American Community Survey

What have we learned?






- Lack of pedestrian facilities
- Limited or no shoulder space
- Pedestrians are present along Sport Hill Road
- Helen Keller Middle School (HKMS) students walk to Village Store
- Connections to Silverman's Farm, Snow's Farm, Sport Hill Farm, and Sherwood Farm are desirable
- Walk connections along Center Road to Morehouse Road desirable



- High traffic speeds (posted 35 MPH, 85th% speed 42-44 MPH)
- Challenging access to driveways and side streets
- Crashes relatively high when compared to other Easton roads
- Generous corner radius on Center Road intersection





- Heavily used by truck, emergency vehicles and farm vehicles
- Mix of land uses
- Some wide driveways
- Seasonal events contribute to localized congestion







3 Community Input

What have we heard?

Do you think safety is an issue within the Sport Hill Road Study Area?



What are your concerns regarding safety within the Sport Hill Road Study Area? (select all that apply)



ANSWER CHOICES

Speeding

Traffic volume/congestion

Confusing to navigate

Difficult to turn into traffic from side streets and driveways

Lack of sidewalks

Lack of shoulders for bicyclists


Poor lighting

Poor visibility


Other (please specify)

Total Respondents: 317

Would you consider walking along the Sport Hill Road Study Area if improvements were made?



Would you consider biking along the Sport Hill Road Study Area if improvements were made?



Snapshot of Input

As a parent my worry is speeding on sport Hill. Children biking and walking home from Keller is a hazard. Reducing the speed of cars and a sidewalk would be fabulous!

I find this project ridiculous. this is not downtown Fairfield. Stop trying to make Easton something it is not.

This project is unnecessary and a waste of taxpayer money.

I support all activities to increase the safety, walkability and bikeability of Easton village area, provided they are done with sensitivity to the character of the village.

Pedestrian safety.
Safety safety. Speeding main problem. Cars do not give pedestrians the right of way.

4

Conceptual Ideas

What is possible?

What are Complete Streets?


Safety

- Consider surrounding land uses, travel needs of residents and users, and other factors.
- Streets designed to be safe and comfortable for people using all modes of transportation and all ages and abilities.
- Pedestrians, bicyclists, public transit users, and drivers.
- Not all streets have to accommodate all users, but a Complete Streets network does serve all users.

Sensitive to Rural Contexts


 Consider surrounding land uses, travel needs of residents and users, and other factors.

Source: Smart Growth America and the National Complete Streets Coalition, 2006



Trail Connections

- Trails can only serve the community if connections are easily made. How?
 - Short on- and off-street connections to cul-de-sacs
 - Pay attention to short, uncomfortable road segments that may discourage use on the whole system




FHWA, 2016

Fireman's Green Intersection Zoom-In



Intersection at Sherwood Farm and Helen Keller Middle School



Sidepaths

Sidepaths, one component of complete streets, can be used on rural roads, where demand is moderate to high and traffic speeds are high.

- Maintain rural character, especially when vegetation is used for separation
- Sidepaths must be placed further back from road at higher speeds (below)


Adjacent Road Speed Limit (Mi/h)	Recommended Sidepath Separation Distance at Crossings
< 25 mi/h	6.5 ft (2.0 m)
35-45 mi/h	6.5-16.5 ft (2.0-5.0 m)
≥ 55 mi/h	16.5-24 ft (5.0-7.0 m)



Transition Zones

- Actual speeds cannot be changed just through speed limit changes; roadway geometry usually must be changed to fit the context.
- Consistent and repeated warnings to drivers are usually required to ensure reduced speeds in towns and villages.

Speeds vs. Spacing of Speed Reduction Measures



Toolbox Examples: Slowing Traffic at Transition Zones


Strategies with a Median


(in more constrained environments)

- Gateway signs
- Narrowing of lanes
- Removal of shoulder
- Sidepath buffer and sidepath
- Appropriate signage and pavement marking
- Median


Rectangular Rapid Flashing Beacon (RRFB)

- A device that rapidly flashes to increase driver yielding rates at uncontrolled intersections.
- Useful for areas where there is a documented low yield rate.





Silverman's Farm Crosswalk Zoom-In



Conditions:
Silverman's
Farm
crosswalk
facing
northwest



Graphic Rendering: Silverman's Farm crosswalk facing northwest




Existing Conditions:

Intersections of Banks Road and Sport Hill Road



Graphic Rendering: **Improvements** at the intersection of **Banks Road** and Sport Hill Road



Existing
Conditions:
Sport Hill
Road facing
north near
Easton Village
Store



Graphic Rendering: Sport Hill Road facing north near Easton Village Store



QUESTIONS?