

Examples of Volunteer Restoration Work

Center Street Cemetery (c. 1860)

Cogswell Obelisk Restoration:

This obelisk was found missing a steel rod necessary to stabilize and connect the piece leaning against the base of the monument. Volunteers used monument compound and epoxy to reset the obelisk shown pictured on the right.



Cogswell Obelisk (After)



Cogswell Obelisk (Before)