

**Examples of Volunteer Restoration Work (2010)**  
**Gilberttown Cemetery (c. 1779)**

Rachel Thorp (Before)



Rachel Thorp (After)



**Summary of Restoration Work:**

Broken Tombstone was found in two separate pieces lying on the ground face up. Compound epoxy and mortar was used to seal and reset this tombstone.